ENGINEERING CHANGE NOTICE DART AEROSPAÇE LTD

20.05.25 Job No.: N/A			ADR Yes/No:	N	ADR Date:	N/A	ECN #	2020 561
			Created By:	MG	Approved By:		EUN #:	2020 561
EC135 CCK			Checked By:	164.62		11885-378		
						-		
9700								
On Pay I								
oo nee. s								
NCR: PAR:		CAR.		CIP:			IIDE:	
		-		_			UKF.	
UPDATE PARTS	MUST	COMPL	Y X	PREVIO	DUS PARTS	SATISFA	CTORY	
ce / Customer Support Actions	Reqd	Resp		No	tes		(omplete
ustomers	N							-
	N							· · · · · · · · · · · · · · · · · · ·
	N					Alexander of the second		***************************************
ensing Agreement Update	N							
Engineering Actions	Louis	Been		N-				
		Resp		No	tes			Complete
	_							
•								
ompatability Matrix								
f Change (eg. ICA, 8110-3)	N							
	7000000000							
Document Control Actions	Pond	Peen		No				`I-A-
		Kesh		NO	les			Complete
		MG				C	201	20.05.25
	_			- 101-11-			Me J	40.03.43
					-			
	_	MG				C	mot .	20.05.25
thorized Release Certificate Database	_						700	20.03.25
hange Record Form / Item Card Database	N			4.00				
	N			No. 24 CHAN				
ed on Packaging Process Plan (PPP)?								
Supplier Documents (Qpulse) Database	N							
ect Binder / Electronic Project Folder	N							
I-Drawing / DSI / DEO Master Binders	N							
Paid to" attribute (Parts sold under Dart USA STC's)	N							
					·			
			And the second second					The state of the s
		,	100			010		2
. Cla	0	let	11 971	Tx	7- 876	887	5 (rkaz.
SLOT	P-	64	6971	5 >	2 326	882	5	CKOZ,
Ja J Stor	p-	64	6971	5 >	2 526	882	s c	CKOZ
Il mod Score	P-	64	6.971	5>	2 526 2 Hl	1882	s c	CKOZ
Il god Sim	p-	64	6-9713	5 > 3	2 \$26 2 HL	1982	s c	ckar
al god sur	P-	64	6.971	5 > 3	2 526 2 HL	1962	s co	ckar
al god Stor	p-	64	6.971 6.9713 .9705	5 7	2 \$26 2 Hh 5th	19	s c	CKOR
al god stor	P-	646	6.971 6.9713 .9705	5 > 3	2 526 2 Hl 5th	19	s c	CKOR
al god stor	P-	646	6.9713 6.9713 .9705	5 - 3	2 526 2 sth 5th	19	s cod	CKOR
	9700 Pev. J NCR: PAR:	PARTS MUST ON Rev. J ON Rev. J	PARTS MUST COMPL Ce / Customer Support Actions Reqd Resp ustomers N Regd Resp ustomers N Regd Resp ustomers N Regd Resp rensing Agreement Update N Regd Resp rensing Agreement Update Regd Resp rensing Agreement Update N Regd Resp rensing Agreement Update Regd Resp rensing Agreement Update N rensing Agreement Update N rensing Agreement Update N Regd Resp rensing Agreement Update N rection Compatability Matrix N Record (RDL) N Record (RDL) N Record (RDL) N Record (Resp rectronic Files / Design Journal N Redd Resp Resp Redd Resp Resp Redd Resp Redd Resp Resp Redd Resp Resp Redd Resp Redd Resp Redd Resp Resp Redd Resp Redd Resp Resp	EC135 CCK Checked By TOO Rev. J COUNTY TOO Rev. J TOO	Record (OR) Document Control Actions Record (OR) Record	B46.4001 Created By: MG Approved By: EC135 CCK Checked By: PAR: CAR: CIR: UPDATE PARTS MUST COMPLY X PREVIOUS PARTS OF COMPLY APPROVED PARTS OF C	Approved By: Approved By:	Created By: MG Approved By: ECN #:

Under Review Notification (URN)

Raised By: J. BECKER							Product #:	URN 20-010, 646.9700			
Date:	05/27/2020	_							Product Name:	CUTTER SUB ASSEMBLY	
	T		_								
	Drawing or Document & Current Affected Revision for each part listed	"Y" or "N" Required for Each Part (do not leave blank)						blank)			
Part Number		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advice Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review ("Bluefiles")	Reserved ECN Log Number	Instructions Relevant to Each Part (including whet serial #s will be affected)	
646.9703	646.9700 H	Yes	Yes	No	No	Yes	Yes	No	06479	MOVE STOCK TO QUARANTINE	
646.9705	646.9700 H	Yes	Yes	No	Yes	Yes	Yes	No	06479	MOVE STOCK TO QUARANTINE	
<u> </u>		-			 -			-			
		-			<u> </u>		<u> </u>				
<u> </u>				ļ	<u> </u>	 					
		-	 		-		-			<u>-</u>	
									<u> </u>		
DESCRIPTION OF ISSUE: DUE TO TOLERANCE ISSUE, THERE IS A HIGH CHANCE THAT INTERFERENCE MAY BE PRESENT BETWEEN THE CUTTER SUB ASSEMBLY AND THE OEM MOUNTING RAIL. P/N 646.9713 AND 646.9715 HAVE BEEN REVISED TO RECTIFY THIS POTENTIAL CLASH. ANY STOCK SHOULD BE QUARANTINED AND BROUGHT TO THE LATEST REVISION ONCE APPROVED.											
✓	Director of Operations Director of Quality Assura Director of Engineering	nce	√ ✓	Docume			s 🗸	Productio	on Planners ng Manager	Regional Sales Manager Product Managers VP Sales	

Linda Lacelle

From: Jacob Becker

Sent: Thursday, May 21, 2020 6:25 PM

To: Michelle GagnonDonovan; Support; Jean-Luc Menard; Konrad Sauve; Ryan Williamson;

> Marcel Daviau; Michael Lee; Victoria Seib; Chris Provencal; Zachary Ficyk; Steven Drouin; Sian Willems; David Duval; Jennifer Renwick; Marie Lajeunesse; Linda Lacelle; Kimberley Guerin; Ross Black; Steven Hemmerich; Robert Aboud; DART SALES ASIA PACIFIC; DART

SALES EMEA RUSSIA; DART SALES LATIN AMERICA; DART SALES NORTH AMERICA

Cc: David Shepherd

Subject: RE: URN 20-010, 646.9703 & 646.9705

Current revision on hold and quarantined. Once the new revision is released, the hold can be lifted. Any current stock is essentially scrap.

Regards,

JACOB BECKER

Lead Sustaining Engineer

DART AEROSPACE

T 1 760 509-1639 M 1 760 691-9108

F 1760758-9612

1-800-556-4166



From: Michelle GagnonDonovan <mgagnondonovan@dartaero.com>

Sent: Thursday, May 21, 2020 12:39 PM

To: Support <support@dartaero.com>; Jean-Luc Menard <jmenard@dartaero.com>; Konrad Sauve

<ksauve@dartaero.com>; Ryan Williamson <rwilliamson@dartaero.com>; Marcel Daviau <mdaviau@dartaero.com>;

Michael Lee <mlee1@dartaero.com>; Victoria Seib <vseib@dartaero.com>; Chris Provencal

<cprovencal@dartaero.com>; Zachary Ficyk <zficyk@dartaero.com>; Steven Drouin <sdrouin@dartaero.com>; Sian

Willems <swillems@dartaero.com>; David Duval <dduval@dartaero.com>; Jennifer Renwick <jrenwick@dartaero.com>;

Marie Lajeunesse <mlajeunesse@dartaero.com>; Linda Lacelle <llacelle@dartaero.com>; Kimberley Guerin

<kguerin@dartaero.com>; Ross Black <rblack@dartaero.com>; Steven Hemmerich <shemmerich@dartaero.com>;

Robert Aboud raboud@dartaero.com; DART SALES ASIA PACIFIC <dartsalesasiapacific@dartaero.com; DART SALES

EMEA RUSSIA <dartsalesemearussia@dartaero.com>; DART SALES LATIN AMERICA

<dartsaleslatinamerica@dartaero.com>; DART SALES NORTH AMERICA <dartsalesnorthamerica@dartaero.com>

Cc: David Shepherd <dshepherd@dartaero.com>; Jacob Becker <jbecker@dartaero.com>

Subject: RE: URN 20-010, 646.9703 & 646.9705

Hello,

I would need some clarification. In the notes of the URN, PN 646.9713 and 646.9715 are referenced. Do these need to be put on hold or quarantined as well? I would like to ensure Plex reflects the correct parts on hold.